Arrival	Departure Telephone		Email			District		
01:35 PM	03:05 PM	281-852-1155					17	
Water Quality								
pH 7.8				nlorine			grafina a financia. Con de Pinnesson de escolega de provinciones de qui accomencente de deligio d	
Temperature			Combined Chlorine		Cyanuric Acid			
Citation(s)		more character and a second of the second of the second or the second of				a di talan matalan di talan matalan garing da madalah di pangan sayah mayah di disabanya mengan mahan sa	
OBSERVATIONS AND CORRECTIVE ACTIONS Code Items in violation to be corrected by the date indicated Correct By								
Code		Items in violation to be corrected by the date indicated						
265.201	Safety	Safety Features for Pools and Spas Safety signs for Pools						
	constructed on or after the effective date of this subchapter or							
	replaced at Pools constructed prior to the effective date of this							
	subchapter shall be in compliance.							
COMMENT	`S			and the second of the second				
Pool passed in	spection.							
Inspector Maria Lugo								
Maria.lugo@houstontx.gov 281-687-7332								
Penny						Date 07/21/2022		
,						Date On En Edez		
Environmental Investigator: MARIA LUGO						Date 07/21/2022		